

Summary

Feature Upgrades

- Feature Upgrade: Drive Recorder
- Feature Upgrade: Welcome Light Animation available in

ConnectedDrive Upgrades

- Feature Upgrade: Welcome Light Animation
- Feature Upgrade: Central Display
- Feature Upgrade: Safety-Related Assistance Systems
- Feature Upgrade: Active Navigation Guidance
- Feature Upgrade: Exterior Light Functions
- Feature Upgrade: BMW Navigation System
- Feature Upgrade: AirConsole Now Part of BMW Digital Premium

Quality improvement:

- Quality improvement: Optimized drive-off behavior
- Quality improvement: Central Display

Service Tasks:

- Service Task: Programming fuel tank control unit
- Service Task: Electric Drive Software Update
- Service Task: AC charging Software Update
- Service Task: Air Freshener Software Update
- Service Task: Navigation Software Update | MGU22
- Service Task: Pedestrian Protection Software Update
- Service Task: Profile Settings Software Update



Feature Upgrade: Drive Recorder

Videos from your Drive Recorder and Anti-Theft Recorder are available in your My BMW App.



Feature Upgrade: Welcome Light Animation available in ConnectedDrive Upgrades

Enhance Welcome Light Animation with three new options available in the ConnectedDrive store: sporty Allegro, dynamic Adagio, and lively Vivace



Feature Upgrade: Welcome Light Animation

Enhanced Welcome Light Animation with three new options: sporty and dynamic Allegro, elegant Adagio, and lively Vivace. Choose your preferred variant in addition to the current animations.





Feature Upgrade: Central Display

This update will personalize your Parking Assistant experience by displaying your chosen BMW Individual two-tone paintwork.



Feature Upgrade: Safety-Related Assistance Systems

Upgrade improves driving safety with warnings for wrong-way entry and no-turn-on-red at intersections. Additionally, get alerts for potential right-of-way violations at traffic lights and stop or yield signs in select states.



Feature Upgrade: Active Navigation Guidance

Lane Guiding with Navigation anticipates necessary lane changes required to reach the guided highway exit. It prompts the driver with a "Initiate Lane change to follow route" notification. Upon confirmation the system actively performs lane changes to reach the exit. In certain situations, manual lane changes are required.

Note: Driver must check visibility, surroundings, and traffic conditions at all times, intervening when needed, and exercising caution to minimizing accident risks.





Feature Upgrade: Exterior Light Functions

Customize locking and unlocking effects with this new update. Choose to enable or disable momentary flashing of headlights, with the option to skip Welcome Light Animation.



Feature Upgrade: BMW Navigation System

When route guidance is active, Augmented View shows you instructions to turn by the navigation system in the central display of your BMW.

Feature Upgrade: AirConsole Now Part of BMW Digital Premium

Turn waiting times into fun with AirConsole Games on your BMW's Curved Display. Use your smartphone as a controller to enjoy over a dozen games, including racing, quizzes, strategy, and puzzles.





Quality improvement: Optimized vehicle drive-off behavior

The drive-off behavior of the vehicle after engine start-stop situations has been improved with this update. The shifting hesitation has been reduced on initial take off.

Quality improvement: Central Display

This upgrade includes faster start for the operating system, smoother scrolling on the central multifunctional instrument display. Optimized display for the Rear View Camera and general improvements to the software.

Service Task: Programming fuel tank control unit.

The current software version of your vehicle may result in the IFM control unit (tank control unit) exhibiting a malfunction, and therefore an engine start no longer being possible. This is rectified by the upgrade.

Service Task: Electric Drive Software Update

Your vehicle's eDrive motor may experience increased wear, indicated by an acoustic noise near the front axle, a "Drive faulty" message, and potential motor failure. This issue is addressed with a software upgrade.

Service Task: AC charging Software Update

This update addresses AC charging issues over 11kW in the current software version with a software upgrade to prevent interruptions.

Service Task: Air Freshener Software Update

Unlock full use of the interior air freshener after installing the software upgrade. (Not available in the current version)

Service Task: Navigation Software Update | MGU22

The current software version of your vehicle may not download the navigation data correctly. This update corrects this issue.



Service Task: Pedestrian Protection Software Update

This upgrade enhances acoustic pedestrian protection.

Service Task: Profile Settings Software Update

The current software version of your vehicle may cause uninitiated changes to profilerelated settings. This update corrects this unwanted behavior in the privacy menu.