


Information about Version Summary



- Personal eSIM: Add your BMW to your existing mobile phone plan
- Lane Departure Warning: More convenient return to original lane after passing vehicles
- Lane Departure Warning: Optimized steering intervention for increased driving comfort
- Programming control units (DME)
- Programming control units (sliding/tilting sunroof)
- Programming control units (telematics control module)
- Improved quality: Improved perception of IconicSounds Sport
- Improved quality: Optimized engine control
- Improved quality: Optimized Hill Descent Control
- Applicability of the Remote Software Upgrade and release notes
- Function updates and quality enhancements
- Information about previous versions
- Updating the on-board Owner's Manual
- Special information about this upgrade
- Specific notes for hybrid vehicles
- Use of the My BMW App for data transfer

Personal eSIM: Add your BMW to your existing mobile phone plan



With Personal eSIM and a compatible mobile phone plan, your vehicle is turned into another device that you can easily link to your monthly plan. The feature uses your vehicle's external antenna to improve phone call clarity and creates a WiFi hotspot in your vehicle, providing up to ten devices with high-speed 5G internet access.

Lane Departure Warning: More convenient return to original lane after passing vehicles



Your vehicle will now detect when you have changed lanes in order to pass another vehicle and will not indicate a Lane Departure Warning or Lane Keep Assist intervention when pulling back into the original lane.

Use of the system does not remove the responsibility of the driver to assess visibility, traffic conditions and to intervene when needed. The driver should always use caution to reduce the risk of accidents.

Lane Departure Warning: Optimized steering intervention for increased driving comfort



This software update provides smoother interventions by the Lane Keep Assist system. As the steering duration and steering forces adapt more to the vehicle speed and position within the lane.

Use of the system does not remove the responsibility of the driver to assess visibility, traffic conditions and to intervene when needed. The driver should always use caution to reduce the risk of accidents.

Programming control units (DME)



This software update resolves a potential error in engine ignition performance.

Programming control units (sliding/tilting sunroof)



This software update prevents the vehicle battery from discharging in the rare case of a mechanical error of the sliding/tilting sunroof or roller sunblind.

Programming control units (telematics control module)



This software update resolves a potential error in the secondary antenna in the telematics control module.

Improved quality: Improved perception of IconicSounds Sport



This software update resolves a potential error in the IconicSounds Sport function.

Improved quality: Optimized engine control



This update provides optimizations to engine control functions.

Improved quality: Optimized Hill Descent Control



This software update provides performance optimizations for the Hill Descent Control function.

Applicability of the Remote Software Upgrade and release notes



You will only be able to use the new functions and enhanced functions provided by this upgrade if your vehicle is equipped with the appropriate features. You can obtain information on the special features of your particular vehicle by consulting the on-board Owner's Manual and using the search function, or by contacting your BMW dealer or the BMW ConnectedDrive hotline.

Function updates and quality enhancements



This Remote Software Upgrade updates existing functions for equipped vehicles and includes quality enhancements.

Information about previous versions



You can read information about all the previous versions of the Remote Software Upgrade in the ConnectedDrive customer portal.



With this Remote Software Upgrade, the on-board Owner's Manual is updated.



It is recommended to perform the Remote Software Upgrade at your home. Park the vehicle outside on a flat surface with a clear view of the sky, avoiding trees or other obstructions. In the unlikely event that you experience issues, the vehicle may not be driven. A BMW Roadside Assistance representative may be able to solve the issue remotely or help to transport your vehicle to the nearest BMW Service Center.

- **IMPORTANT INFORMATION:** Please remove all OBD diagnostic devices (trip books, GPS trackers) before starting and during the upgrade.
- **IMPORTANT INFORMATION:** Certain services may not run or may be limited until this upgrade is installed.
- Reloading the ConnectedDrive apps after the upgrade can take some time.
- Only leave and lock your car once the countdown for the upgrade is completed.
- Some settings may be reset to default after the upgrade (for example, Remote Engine Start, Connected Music or notification settings) and need to be re-activated.
- Restarting some vehicle systems may cause control messages to appear on the display during or after an upgrade. Please pay attention to these control messages and observe whether they are still shown after the restart (e.g., parking brake, drivetrain malfunction).
- **IMPORTANT INFORMATION for iOS Users:** when transferring the upgrade using your smartphone, please connect via the Bluetooth & Wi-Fi connection in the vehicle and the "Mobile devices" menu. If the Bluetooth and/or Wi-Fi icon appears greyed out, please first activate Apps & Bluetooth Audio in the settings in the submenu of "Mobile devices".
- **IMPORTANT NOTE for M vehicles:** The installation prompt for the Remote Software Upgrade can only be displayed approx. 30-60 minutes after engine switch-off because the engine needs to cool down. The prompt is displayed before engine start. The next time you enter your vehicle, please perform the installation before starting the engine and wait until the installation prompt is displayed.
- **IMPORTANT NOTE for Users of BMW Drive Recorder:** The initial settings will be reset, and recorded videos deleted after the upgrade. Please download videos you would like to keep prior to beginning the upgrade.
- Please note that conversions/retrofits/tuning or special encoding, etc. on the vehicle that has not been approved by BMW AG ("BMW") may be lost as a result of a remote software upgrade or lead to significant problems (up to and including consequential damage) during and after vehicle programming. BMW and BMW service outlets accept no liability for any resulting damage.

Specific information for electric / Plug-in hybrid vehicles



- If you perform the Remote Software Upgrade during charging, the charging process will be interrupted and will not automatically continue. Complete charging before starting the upgrade.
- Charging and climate control settings can be reset after the Remote Software Upgrade (e.g., charging settings to 6A instead of 16A). Once you have completed the upgrade, reset your preferences in the relevant menus under Settings.

Use of the My BMW App for data transfer



NOTE: You can find out how to use the My BMW App for data transfer on YouTube, by visiting <https://www.youtube.com/watch?v=7avD14vNiwg> or scanning the QR code displayed above.

We look forward to receiving your feedback on the BMW ConnectedDrive hotline. Call 1 (888) 333-6118 to help us to continually optimize our Remote Software Upgrade.